



JON M. HUNTSMAN, JR.  
Governor

GARY R. HERBERT  
Lieutenant Governor

# State of Utah

## DEPARTMENT OF NATURAL RESOURCES

### Division of Oil, Gas & Mining

MICHAEL R. STYLER  
Executive Director

JOHN R. BAZA  
Division Director

### Inspection Report

#### Minerals Regulatory Program

January 19, 2007

Supervisor DRH

**Mine Name:** Jim Gay Mine

**Operator Name:** Interstate Brick Company

**Permit number:** M0490005

**Inspection Date:** June 7, 2006

**Time:** 11:15 am

**Inspector(s):** Lynn Kunzler and Daron Haddock, DOGM

**Other Participants:** none

**Mine Status:** Active

Elements of Inspection	Evaluated	Comment	Enforcement
1. Permits, Revisions, Transfer, Bonds	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>	<input type="checkbox"/>
2. Public Safety (shafts, adits, trash, signs, highwalls)	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
3. Protection of Drainages / Erosion Control	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
4. Deleterious Material	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
5. Roads (maintenance, surfacing, dust control, safety)	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
6. Concurrent Reclamation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
7. Backfilling/Grading (trenches, pits, roads, highwalls,	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
8. Soils	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
9. Revegetation	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
10. Other	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>

#### Purpose of Inspection:

This was a routine inspection while in the area.

#### Inspection Summary:

This site is considered active, although there was no activity during the time of this inspection.

Upon arrival at the site, a large area to the northwest appeared to have been recently reclaimed. Later conversation with the operator identified this area as the BLM trespass area that they had reclaimed to satisfy the BLM. The area is within the permit area. There was also a large stockpile of clay to the south of the permit area. Since this had never been observed before, initially it was thought that they had placed this stockpile outside the permit area. The area was surveyed with the GPS unit.

Photos were taken to document site conditions.

#### Conclusions and Recommendations:

Examination of the permit area map (upon return to the office), showed that the new stockpile area was within the permitted and bonded area. This operation is in compliance at this time.

Continue to monitor this site when in the area.

**Inspector's Signature**

[Signature]

**Date:** January 19, 2007

LK:pb

O:\M049-Utah\M0490005-JimGayMine\inspections\Insp-06072006.doc